



**National
Transportation
Safety Board**

SpaceShip Two: The Anatomy of a Commercial Space Accident

Robert Sumwalt

Presentation to Academie de L'Air et du L'Espace

In-Flight Breakup During Test Flight

October 31, 2014


SpaceShip Two




NTSB




NTSB




NTSB



SpaceShipTwo Feather System



Feather retracted



Feather extended



NTSB

SpaceShipTwo Flight Deck



NTSB



Feather extend handle



PROBLEM: During the transonic region, the upward aerodynamic forces acting on the feather exceeded the ability of the feather actuators to keep the feather retracted.

SOLUTION:
Provide
mechanical
locks to keep
feather
retracted during
this region.



Feather Lock Handle



Feather Locked

Lock



Unlock




Feather Unlocked

PROBLEM: If feather could not be unlocked, it would pose a very high risk (probably catastrophic) reentry.

SOLUTION: Unlock feather at 1.4 Mach.

If not unlocked at 1.5 Mach, cockpit alert.
If not unlocked at 1.8 Mach, mission abort.



NTSB

- High emphasis on making sure feather was unlocked.
 - Cockpit visual and aural alerting
 - Training and procedures
 - Mission abort if not unlocked by 1.8 Mach
- Not great concern placed on low speed unlocking.
 - Relied on pilots to do it right



Specified Flight Crew Procedures

PILOT

Action: Vehicle control
Verbal command: "Fire"

WK2 release

COPILOT

Action:
Ignite rocket motor



Specified Flight Crew Procedures

PILOT

Action: Vehicle control
Verbal command: "Fire"

WK2 release

0.8 Mach

COPILOT

Action:
Ignite rocket motor

Verbal call:
"0.8 Mach"



Specified Flight Crew Procedures

PILOT

Action: Vehicle control
Verbal command: "Fire"

Action:
Trim stabilizer

WK2 release

0.8 Mach

Transonic bobble

COPILOT

Action:
Ignite rocket motor

Verbal call:
"0.8 Mach"

Verbal call:
"Stabs (degrees)"



Specified Flight Crew Procedures

PILOT

Action: Vehicle control
Verbal command: "Fire"

Action:
Trim stabilizer

WK2 release

0.8 Mach

Transonic bobble

1.4 Mach

COPILOT

Action:
Ignite rocket motor

Verbal call:
"0.8 Mach"

Verbal call:
"Stabs (degrees)"

Action:
Unlock feather



What actually occurred

- Copilot made 0.8 Mach callout
- At 0.82 Mach, called out “unlocking” and moved feather handle to unlocked position
- Video and telemetry stopped



NTSB



Ground-based camera



WhiteKnightTwo camera

SpaceShipTwo camera



DCA15MA019
SCALED COMPOSITES
SPACESHIP TWO
N339SS
POWERED FLIGHT #4



NTSB

- A single-point mechanical failure with catastrophic consequences would be unacceptable.
- However, Scaled Composites failed to consider that a single human error could be catastrophic.



NTSB Finding

“By not considering human error as a potential cause of uncommanded feather extension on the SpaceShipTwo vehicle, Scaled Composites missed opportunities to identify the design and/or operational requirements that could have mitigated the consequences of human error during a high workload phase of flight.”



Probable Cause of the Accident

- “Scaled Composites’ failure to consider and protect against the possibility that a single human error could result in a catastrophic hazard to the SpaceShipTwo vehicle.
- This failure set the stage for the copilot’s premature unlocking of the feather system as a result of time pressure and vibration and loads that he had not recently experienced, which led to uncommanded feather extension and the subsequent aerodynamic overload and in-flight breakup of the vehicle.”





National Transportation Safety Board